



2015091059U

检测报告

报告编号 EDD35I000289

第 1 页 共 12 页

委托单位 常州市环境科学研究院

地 址 常州市新北区横山路 18 号

检测类别 工业废气

编制: 马媛媛

审核: 王天进

批准: 陈卫东

日期: 2016.02.06

陈卫东
实验室经理

采样日期: 2016年02月03日

检测日期: 2016年02月03日~2016年02月06日

上海华测品标检测技术有限公司

上海市浦东新区新金桥路 1996 号

No. 1758022649

检测报告

报告编号 EDD35I000289

第 2 页 共 12 页

样品信息:

检测类别	检测点	采样人	采样方式	样品状态
工业废气	详见 (1)	阙康勇、张方哲、 王晓琛	连续	吸附管、气瓶、滤膜

检测性质 委托检测

附:检测布点图



说明: ○废气无组织采样点

检测报告

报告编号

EDD35I000289

第 3 页 共 12 页

检测结果:

(1) 工业废气 (无组织)

检测项目		结果		
		排放浓度 mg/m^3		
		新北区政府北侧	外国语学校	项目地块内
VOCs	1,1-二氯乙烯	ND	ND	ND
	二氯甲烷	7.43×10^{-3}	6.44×10^{-3}	5.93×10^{-3}
	反 1,2-二氯乙烯	ND	ND	ND
	1,1-二氯乙烷	ND	ND	ND
	顺 1,2-二氯乙烯	ND	ND	ND
	溴氯甲烷	ND	ND	ND
	氯仿	ND	ND	ND
	2,2-二氯丙烷	ND	ND	ND
	1,2-二氯乙烷	ND	ND	ND
	1,1,1-三氯乙烷	ND	ND	ND
	1,1-二氯丙烯	ND	ND	ND
	四氯化碳	ND	ND	ND
	苯	5.92×10^{-3}	5.96×10^{-3}	7.72×10^{-3}
	二溴甲烷	ND	ND	ND
	1,2-二氯丙烷	ND	3.04×10^{-2}	ND
	三氯乙烯	ND	ND	ND
	溴二氯甲烷	ND	ND	ND
	反 1,3-二氯丙烯	ND	ND	ND
	顺 1,3-二氯丙烯	ND	ND	ND
	1,1,2-三氯乙烷	ND	ND	ND
	甲苯	3.32×10^{-3}	4.66×10^{-3}	3.40×10^{-3}
	1,3-二氯丙烷	ND	ND	ND

检测报告

报告编号

EDD35I000289

第 4 页 共 12 页

检测项目		结果		
		排放浓度 mg/m ³		
		新北区政府北侧	外国语学校	项目地块内
VOCs	二溴氯甲烷	ND	ND	ND
	1,2-二溴乙烷	ND	ND	ND
	四氯乙烯	ND	ND	ND
	1,1,1,2-四氯乙烷	ND	ND	ND
	氯苯	ND	ND	ND
	乙苯	ND	ND	ND
	对（间）二甲苯	ND	ND	ND
	溴仿	ND	ND	ND
	苯乙烯	ND	ND	ND
	邻二甲苯	ND	ND	ND
	1,2,3-三氯丙烷	ND	ND	ND
	1,1,2,2-四氯乙烷	ND	ND	ND
	异丙苯	ND	ND	ND
	溴苯	ND	ND	ND
	正丙苯	ND	ND	ND
	2-氯甲苯	ND	ND	ND
	4-氯甲苯	ND	ND	ND
	1,3,5-三甲苯	ND	ND	ND
	叔丁苯	ND	ND	ND
	1,2,4-三甲苯	ND	ND	ND
	仲丁苯	ND	ND	ND
	1,3-二氯苯	ND	ND	ND
	1,4-二氯苯	ND	ND	ND
	对异丙基甲苯	ND	ND	ND
	1,2-二氯苯	ND	ND	ND
	正丁苯	ND	ND	ND
	1,2-二溴-3-氯丙烷	ND	ND	ND
	1,2,4-三氯苯	ND	ND	ND
	萘	ND	ND	ND
	六氯丁二烯	ND	ND	ND
	1,2,3-三氯苯	ND	ND	ND